



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:								
Company	Charles Reynolds							
OGM	Steve Demczak							

Inspection Report

Permit Number:	C0070011
Inspection Type:	PARTIAL
Inspection Date:	Thursday, July 29, 2010
Start Date/Time:	7/29/2010 10:00:00 AM
End Date/Time:	7/29/2010 2:00:00 PM
Last Inspection:	Tuesday, June 29, 2010

Inspector: Steve Demczak,

Weather: Sunny, 80's

InspectionID Report Number: 2444

Accepted by: jhelfric

8/3/2010

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC

Site: HIAWATHA MINE COMPLEX

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	12,177.00
Total Disturbed	290.00
Phase I	95.90
Phase II	
Phase III	

Mineral Ownership 1

Types of Operations

✓ Federal
✓ Underground

✓ State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demozak,

Date

Tuesday, August 03, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070011Inspection Type: PARTIAL

Inspection Date: Thursday, July 29, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	<u> </u>		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations	V		✓	
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				П

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Thursday, July 29, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There seems to be a real possibility that the owner of Bear Canyon will have to do some permitting at Hiawatha. The courts may decide some of the Hiawatha disturb area is part of Bear Canyon.

3. Topsoil

Some of the topsoil piles were inspected with no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

The permittee corrected the uncontrolled water at #4 and #5 Mine.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

All impoundment contained little to no water. No hazardous conditions were noticed.

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse piles were spot checked with no hazardous conditions noticed during the inspection.

8. Noncoal Waste

The permittee has finished the clean up of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

15. Cessation of Operations

No activity at the slurry ponds were noticed.